

~~SECRET~~

25X1A2g

25X1A2g

[REDACTED] CITE [REDACTED] TWO ONE FIVE TWO

25X1A2g

OPCEN PASS [REDACTED]

25X1A2g

1. HTA DASH THREE EXPERIENCING PROCESSING PROBLEM CAUSING
DELAY IN INTERPRETATION AND PREPARATION OF ODE REPORT ON
MISSION FOUR ZERO ONE EIGHT. [REDACTED] DASH THREE QUALITY APPEARS 25X1A2g
BEST TO DATE (ON PORTION OF ONE ROLL PROCESSED.)

2. FILM ADHERES TO ITSELF IN FIRST WETTING BATH AFTER TAKE-OFF
FROM CAMERA MAGAZINE TO PROCESSOR.

3. SOLUTION TO THIS PROBLEM APPEARS TO BE A WETTING BATH
BETWEEN SUPPLY REEL AND PROCESSOR REEL SO THAT FILM IS THOROUGHLY
WET WHEN WOUND ON THE PROCESSOR.

4. LOCALLY FABRICATING NECESSARY DEVICE AND WILL CONTINUE
PROCESSING IN MATTER OF HOURS.

CFN: HTA DASH TAKE DASH OFF A.

~~SECRET~~